

KU-KEN-003

No.TCD-562-69

Date January 7, 1969

Japan Civil Aviation Bureau

Airworthiness Directive

The undermentioned examinations or modifications are mandatory.

1. Applies to: NAMC Model YS-11 Airplane (S/N 002, S/N 2003 thru S/N 2049)

2. Compliance required as indicated

To increase the strength of the box beam rib (W. STA. 2908), unless already accomplished, reinforce the affected rib prior to the next D-check (every 4,000 flight hours) in accordance with paragraph 2. Accomplishment Instructions, NAMC Service Bulletin, dated December 17, 1968, or later JCAB approved revisions. No.57-37

3. Remarks.

3.1 Effective date: January 25, 1969

3.2 NAMC Service Bulletin, dated December 17, 1968 covers this subject.  
No.57-37