

KU-KEN- 17

No.TCD- 707-71

Date Jan. 27, 1971

Japan Civil Aviation Bureau

Airworthiness Directive

The undermentioned examinations or modifications are mandatory.

1. Applies to: NAMC Model YS-11 and YS-11A Series Airplanes

2. Compliance required as indicated

To prevent the mis-alignment of the main entrance door locking racks, within the next 50 hours' time in service after the effective date of this AD, unless already accomplished, install a placard on the main entrance door central panel in accordance with NAMC Service Bulletin No. 52-81 dated January 16, 1971 or later JCAB approved revisions.

Placard wording is as follows:

CAUTION

1. DOOR OPEN

DO NOT OPEN DOOR BEFORE CABIN DIFFERENTIAL
PRESSURE REDUCED TO ZERO

2. DOOR CLOSE

CONFIRM DOOR LATCHES ARE IN LOCKING POSITION
BY VISUAL CHECK

Japan Civil Aviation Bureau	No.TCD- 707-71	Sheet 2
<p>3. Remarks</p> <p>3.1 Effective date; February 5, 1971</p> <p>3.2 NAMC Service Bulletin No. 52-81 and Service News YS-11-126 refer to this subject.</p>		