

KU-KEN- 288

No.TCD-976-74

Date April 24, 1974

Japan Civil Aviation Bureau

Airworthiness Directive

The undermentioned examinations or modifications are mandatory.

1. Applies to: NAMC Model YS-11 and YS-11A series airplanes equipped with AiResearch Model GTCP 36-16 APU

2. Compliance required as indicated

To prevent possible fire caused by the malfunction of the APU wiring harness, unless already accomplished, comply before May 1, 1974 with the Accomplishment Instructions of the NAMC Service Bulletin No. A49-13 dated Feb. 25, 1974.

3. Remarks

( a ) Effective date ; April 25, 1974

( b ) NAMC YS-11 Service Bulletin No. A49-13 dated Feb. 25, 1974  
pertains to this subject.