

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3 0 0 8	DATE	Jul. 2 7 . 2 0 1 2
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	Because two-point seat belts are attached to the second row seat of the vehicle for police, the vehicle does not comply with the Japanese regulation.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
ABG-DVW41	C I V I L I A N	2 0 1 2	1
		TOTAL	1