VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2994	DATE	July, 30, 2012	
MANUFACTURER		FUJI AUTO BODY CO.,	LTD.	
DESCRIPTION OF DEFECT	Due to the inappropriate lit color of lamps for checking whether compartment door locks on van-type freight trucks are locked, such red lamps, which can remain lit during travel when a lock is unlocked by a remote key, infringe on restrictions on lamps, etc. as stipulated in Article 42 of the Safety Regulations for Road Vehicles.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
PB-XZU411	TOYOTA DYNA	2006	8
BDG-XZU414		2007~2008	6
BKG-XZU414		2008	3
BDG-XZU548		2007	1
GE-RZH112K	TOYOTA HIACE VAN	2005	1
LD-BZU410M	- HINO DUTRO	2006	2
BDG-XZU334M		2007~2008	4
KR-NKR81LV	ELF	2004	1
TC-SK82V	BONGO	2006	1
_		TOTAL	27