

VEHICLE SAFETY/POLLUTION REGALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3006	DATE	July. 30. 2012
MANUFACTURER	NISHO-REITO CO., LTD.		
DESCRIPTION OF DEFECT	Due to the inappropriate lit color of lamps for checking whether compartment door locks on chilled/frozen refrigerator trucks are locked, such red lamps, which can remain lit during travel when a lock is unlocked by a remote key, infringe on restrictions on lamps, etc. as stipulated in Article 42 of the Safety Regulations for Road Vehicles.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TE-S200P	HIJET	2004~2006	7
		TOTAL	7