VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3055	DATE	Nov.14.2012	
MANUFACTURER	TOYOTA			
DESCRIPTION OF DEFECT	hardness on the ge which connects stee possibility that back extension shaft if the to the full-lock posit is continuously oper wear out, which cou #2 In the electric water is a possibility that improper coiling may wire may corrode a could lead to illumin mode. If short ci for the electric pow unable to be operate Inverter: Electrical	ar box side of the incering wheel to the step dash may develop at the steering wheel is frequency too while driving at a reated in this condition, and result in loss of steer are pump for the inverter the coil wire may have anufacturing process. In the break, causing the mation of warning lights recuit occurs between a ver supply may blow, d.	chicles, due to insufficient termediate extension shaft tering gear box, there is a ne connected portion of the uently and forcefully turned slow speed. If the vehicle the connected portion may ing ability. of the hybrid system, there is been scratched due to the In this condition, the coil water pump to stop, which is or a limited motive power diacent coil wires, the fuse causing the vehicle to be changes high-voltage direct	

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF	NOTE
	NAME	RECALLED	VEHICLE	
ZA-NHW20	PRIUS	2003-2004	61,137	#1,2:10,476
DAA-NHW20				#1: 50,661
		2004-2011	170,700	#1,2:90,961
				#1:79,739
		2004-2007	24,045	#1,2:2,112
				#1:21,933
		2006-2009	89,262	#1,2:60,983
				#1:28,279

ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	NOTE
UA-ZNE10G	WISH	2003-2009	366,050	#1
CBA-ZNE10G			,	
DBA-ZNE10G				
UA-ANE10G		2003-2009	30,880	
CBA-ANE10G				
DBA-ANE10G				
CBA-ZNM10G	Isis	2004-2009	59,936	
CBA-ZNM10W				
CBA-ANM10G		2004-2009	33,393	
DBA-ANM10G				
TA-NZE120	COROLLA	2000-2006	5,777	
UA-NZE120				
CBA-NZE120		2000-2006	11,924	
TA-NZE121	COROLLA	2000-2006	126,225	
UA-NZE121	COROLLA RUNX			
CBA-NZE121	ALLEX	2000-2006	136,909	
DBA-NZE121				
		2001-2006	82,542	
UA-ZZE122		2002-2006	7,244	
CBA-ZZE122				
		2002-2006	4,880	
		2002-2006	10,727	
TA-NZE121G	COROLLA FIELDER	2000-2005	135,012	
UA-NZE121G				
CBA-NZE121G		2005-2006	36,190	
DBA-NZE121G				
TA-ZZE122G		2002-2005	22,760	
UA-ZZE122G				
CBA-ZZE122G		2005-2006	6,940	

OMMERCIAL NAME DROLLA SPACIO WILL VS	MODEL YEAR RECALLED 2001-2007 2002-2004	NUMBER OF VEHICLE 81,728	NOTE #1
DROLLA SPACIO	2001-2007	81,728	#1
			#1
WiLL VS	2002-2004	3,193	
WiLL VS	2002-2004	3,193	
WiLL VS	2002-2004	3,193	
]	
PHARD HYBRID	2003-2008	6,050	#2
STIMA HYBRID	2001-2002	1,684	
	2002-2005	2,358	
CROWN SEDAN	2002-2008	527	
YOTA FCHV-adv	2008	25	
	TOTAL		1,518,098
	STIMA HYBRID ROWN SEDAN	2001-2002 2002-2005 ROWN SEDAN 2002-2008 YOTA FCHV-adv 2008	STIMA HYBRID 2001-2002 1,684 2002-2005 2,358 ROWN SEDAN 2002-2008 527 YOTA FCHV-adv 2008 25

#1 1,507,454

#2 175,176