

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3432	DATE	Sep.11 2014
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	<p>① On light-duty trucks and buses with automated manual transmission, strength of the hose for transmission oil cooler is insufficient, and cracks may occur inside the hose due to pressure fluctuation in the hose. If the vehicle continues to be used in this condition, the cracks will grow and, beaten by the pressure, the hose will rupture to leak oil. In the worst case, the vehicle will become unable to run. Furthermore, leaked oil may endanger other traffic.</p> <p>② On light-duty trucks, the resin part of the fuel pump may crack due to the ultraviolet ray degradation and the residual stress from manufacturing process. If the vehicle continues to be used in this condition, the cracks will grow and the fuel will leak.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SJG-FEA53	「FUSO CANTER」	2011~2011	3
SKG-FBA00		2010~2013	1,543
SKG-FBA20		2010~2013	3,223
SKG-FBA30		2010~2013	991
SKG-FBA60		2010~2013	1,861
SKG-FDA00		2011~2012	359
SKG-FDA20		2011~2012	187
SKG-FDA40		2011~2012	92
SKG-FEA20		2010~2013	664
SKG-FEA50		2010~2013	3,142
SKG-FEA70		2010~2013	83
SKG-FEA80		2011~2012	163
SKG-FEB20		2010~2013	270
SKG-FEB50		2010~2013	3,449
SKG-FEB70		2010~2013	539
SKG-FEB80		2011~2012	805
SKG-FEB90		2010~2012	1,281
SKG-FEC90		2010~2014	64
SKG-FGA20		2011~2012	119
SKG-FGB70		2011~2012	80
TKG-FBA20		2011~2014	4,265
TKG-FBA30		2010~2014	1,454
TKG-FBA50		2013~2014	782
TKG-FBA60		2011~2014	2,898
TKG-FDA20		2011~2014	730
TKG-FDA40		2011~2014	336
TKG-FDA50		2014	1
TKG-FEA20		2011~2014	1,399
TKG-FEA50		2011~2014	4,711

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TKG-FEA80	「FUSO CANTER」	2011～2014	679
TKG-FEB20		2011～2014	428
TKG-FEB50		2011～2014	5,129
TKG-FEB80		2011～2014	2,266
TKG-FEB90		2011～2014	2,277
TKG-FEC90		2011～2014	135
TKG-FGA20		2012～2014	539
TKG-FGB70		2011～2014	241
TPG-FBA00		2011～2014	3,876
TPG-FBA20		2012～2014	41
TPG-FBA50		2013～2013	4
TPG-FBA60		2013～2014	4
TPG-FDA00		2011～2014	1,135
TPG-FDA20		2012～2013	10
TPG-FDA40		2012～2013	4
TPG-FEA20		2012～2014	107
TPG-FEA50		2012～2014	19
TPG-FEA80		2012～2014	5
TPG-FEB20		2012～2013	19
TPG-FEB50		2012～2013	66
TPG-FEB80		2012～2014	29
TPG-FEB90		2012～2014	32
TPG-FEC90		2014	1
TPG-FGA20		2012～2013	4
TQG-FEA13		2012～2014	72
TQG-FEA53		2012～2014	448
TQG-FEB73		2012～2014	384
TRG-FBA00		2012～2014	69
TRG-FDA00		2012～2014	25
SKG-BE640G		「FUSO ROSA」	2011～2012
SKG-BE640J	2011～2012		41
TPG-BE640E	2013～2014		91
TPG-BE640G	2011～2014		999
TPG-BE640J	2011～2014		220
TRG-BE640J	2012～2013		9
TKG-FBA3W	「ATLAS」	2013～2014	38
TKG-FBA5W		2013～2014	79
TKG-FEA5W		2013～2014	104
TKG-FEB5W		2013～2014	66
TKG-FGB7W		2013～2014	5
TPG-FBA2W		2013～2014	9

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
TPG-FBA5W	「ATLAS」	2013～2014	42	
TPG-FBA6W		2013～2014	25	
TPG-FDA2W		2013～2014	65	
TPG-FDA4W		2013～2014	18	
TPG-FEA2W		2013～2014	30	
TPG-FEA5W		2013～2014	53	
TPG-FEA8W		2013～2013	2	
TPG-FEB2W		2013～2014	27	
TPG-FEB5W		2013～2014	34	
TPG-FEB8W		2012～2014	213	
TPG-FEB9W		2013～2014	32	
TPG-FGA2W		2013～2014	23	
TPG-FGB7W		2013～2014	6	
TQG-FEA5X		2013～2014	12	
TQG-FEB7X		2013	1	
		TOTAL	56,014	