## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2145	DATE	Feb 12, 2015		
MANUFACTURE	General Motors Company				
	(Japanese Importer: General Motors Japan Ltd. )				
DESCRIPTION OF DEFECT	General Motors has decided that a defect which relates to motor vehicle safety exists in certain 2014 model year Chevrolet Corvette vehicles. An improper weld on the rear shock absorbers may lead to separation of the shock absorber tube from				
52.20.					
	the shock absorber clevis bracket. This separation may cause a sudden cha				
	vehicle handling behavior that may startle drivers, increasing the risk of a crash.				

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF
	NAME	RECALLED	VEHICLE
「Unknown」	「Corvette」	2014	11
		TOTAL	11