VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

			-	
CAMPAIGN No.	GAI-2162	DATE	March 25, 2015	
MANUFACTURER	Volkswagen (Japanese Importer: Volkswagen Group Japan KK)			
DESCRIPTION OF DEFECT	 ① Due to a combination of production tolerance issues and vehicle vibration during dynamic driving, it is possible that, in rare cases, a fuel leak may occur in the vehicle's fuel injection system. Leaking fuel, in the presence of an ignition source, may result in a fire. ② Additionally, some vehicles may benefit from having the thermostat replacement. 			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DAA-7PCGEA	「VW Touareg V6 3.0 Hybrid」	MY2011-MY2012	298
		Total	298