VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

RECALL No.	Gai-2156	DATE	Mar. 13, 2015	
MANUFACTURER	Ford Motor Company			
	(Japanese Importer: Ford Japan Limited)			
DESCRIPTION OF	SAFETY RECALL: Certain 2013 Model Year Focus Vehicles			
	- Focus Front Drive Half shafts Replacement			
DEFECT	Certain Focus vehicles have been fitted with front drive half shafts			
	that have a reduced wall thickness and therefore a reduced load carrying			
	capacity. Under cer	tain conditions the ha	lf shafts may fracture.	

ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-MPBMGD	Focus	2013	440 unit
		TOTAL	440 units