VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3 6 0 1	DATE	As soon as it is ready
MANUFACTURER	NISSAN		
DESCRIPTION OF DEFECT	On the particular inflator of front passenger airbag, the cause does not become clear, but replaces the inflator with a new one as preventive measures because the inflator container may be ruptured when the air bag is deployed.		

ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
CBA-Y50 DBA-Y50	FUGA	2007~2008	5, 062
CBA-PY50 DBA-PY50			5, 758
CBA-PNY 5 0 DBA-PNY 5 0			977
CBA-GY50			979
CBA-J31	TEANA	2007~2008	6, 575
СВА-РЈ31			2 1 4
CBA-TNJ31			9 1 9
DBA-TU31	PRESAGE	2007~2009	5, 870
DBA-TNU31			1, 277
CBA-PU31			4 6 9
CBA-NT30	X-TRAIL	2007	1 3 0 6
CBA-T30			3 1 2
GH-PNT30			7 6
TA-WFGY61	SAFARI	2007	4 1

ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
CBA-SGE 2 5	CARAVAN	2007~2009	1, 533
CBA—SE25			5 8 5
TA-QGE 2 5			282
TA-QE25			1 0 4
LC-CQGE25			4 5
KR-CWGE 2 5 ADF-CWGE 2 5			1 2 1
KR-CWMGE 2 5 ADF-CWMGE 2 5			1 9 4
CBF-CSGE25			2 1 6
KR-VWE 2 5 ADF-VWE 2 5			5 3 5
KR-VWME 2 5 ADF-VWME 2 5			5 2 8
CBF-VRE 2 5			473
L C - V P E 2 5			8 1
CBF-DSGE 2 5			7 6 8
LC-DQGE25			6 6
KR-DWGE 2 5 ADF-DWGE 2 5			4 5
KR-DWMGE 2 5 ADF-DWMGE 2 5			462
CBA-JSGE25	ISUZU COMO	2007~2008	2 2
CBA-JSE25			6
TA-JQGE25			1
TA-JQE25			1
ADF-JCWGE25			2
KR-JCWMGE25 ADF-JCWMGE25			3
CBF-JCSGE25			3
KR-JVWE 2 5 ADF-JVWE 2 5			1 8

ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
KR-JVWME 25 ADF-JVWME 25	ISUZU COMO	2007~2008	1 3
CBF-JDSGE25			1
ADF-JDWGE25			1
KR – J DWMG E 2 5			2
		TOTAL	35, 946