VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2197	DATE	June 19, 2015
MANUFACTURE	Automobiles PEUGEOT		
	(Japanese Importer :	PEUGEOT CITROËN JA	PON Co.,Ltd.)
DESCRIPTION OF DEFECT	Because faulty part may be fitted on electrical board of the cooling fan, it may fail to operate even if the coolant gets heated. Therefore, if it kept in use, engine might be overheated and in very exceptional circumstances, it may burn.		

ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
GH-D2BRV	PEUGEOT 407	2005 - 2006	492
GH-D2CPV	PEUGEOT 407 Coupe	2006	6
GH-D2V	PEUGEOT 407	2005 - 2006	447
		TOTAL	945