VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN



CAMPAIGN No.	GAI-2282	DATE	December 11, 2015
MANUFACTURER	MASERATI S.p.A. (Japanese Importer: Maserati Japan Ltd.)		
DESCRIPTION OF DEFECT	Vehicles were manufactured with door latch mechanisms with insufficient heat treatment. The heat treatment process is necessary especially for door latch mechanisms, and in the event of a vehicle accident the doors may open involuntarily.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
ABA-MGTS2	GranTurismo Sport	2015	1
ABA-MGTA1	GranTurismo Sport Automatic	2015	3
ABA-MMCS1	GranTurismo MC Stradale	2015	1
ABA-MGCS1	GranCabrio Sport	2015	3
		TOTAL	8