

**VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN**

**Domestic Vehicles**

CAMPAIGN No.	4018	DATE	Mar.30.2017
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	<p>In the front passenger airbag inflator of the subject vehicles, due to insufficient protection against moisture absorption into the propellant, there is a possibility that the propellant could degrade after several years of exposure to temperature and moisture fluctuations. In this condition, the inflator may rupture in the event the airbag is activated.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-NZE141	[COROLLA AXiO]	2010	10,728
DBA-NZE144			1,190
DBA-ZRE142			628
DBA-ZRE144			120
DBA-NZE141			10,266
DBA-NZE144			985
DBA-ZRE142			478
DBA-ZRE144			97
DBA-NZE141		2011-2012	16,913
		2011	3,662

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-NZE144	[COROLLA AXiO]	2011-2012	3,008
		2011	455
DBA-ZRE142	[COROLLA AXiO]	2011-2012	698
		2011	160
DBA-ZRE144	[COROLLA AXiO]	2011-2012	191
		2011	34
DBA-NZE141G	[COROLLA FIELDER]	2010	17,206
DBA-NZE144G			3,301
DBA-ZRE142G			1,542
DBA-ZRE144G			527
DBA-NZE141G			14,907
DBA-NZE144G			2,345
DBA-ZRE142G			1,930
DBA-ZRE144G			632
DBA-NZE141G		2011-2012	27,611
DBA-NZE144G			5,767
DBA-ZRE142G			3,277
DBA-ZRE144G			1,525

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-NZE151N	[COROLLA RUMION]	2010	5,890
DBA-ZRE152N			2,682
DBA-ZRE154N			1,011
DBA-NZE151N			4,213
DBA-ZRE152N			1,519
DBA-ZRE154N			670
DBA-NZE151N		2011	2,731
DBA-ZRE152N		2011-2012	6,773
DBA-ZRE154N		2011	1,177
DBA-ZRE154N		2011-2012	2,476
DBA-NZE151H	[AURIS]	2010	580
DBA-NZE154H			1,200
DBA-ZRE152H			6,271
DBA-ZRE154H			1,176
DBA-NZE151H			2,211
DBA-NZE154H			337
DBA-NZE154H			4,433
DBA-NZE154H			912

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-ZRE152H	[AURIS]	2010	1,225
DBA-ZRE154H			204
DBA-NZE151H		2011	3,922
DBA-NZE154H		2011-2012	1,894
DBA-ZRE152H		2011	750
DBA-ZRE154H		2011-2012	438
DBA-ZRE152H		2011	1,043
DBA-ZRE154H		2011-2012	452
DBA-ZRR70G	[NOAH] [VOXY]	2011	247
DBA-ZRR70W		2011-2012	107
DBA-ZRR75G		2010	25,363
DBA-ZRR75W			33,176
DBA-ZRR70G			4,134
DBA-ZRR70W			5,705
DBA-ZRR75G			20,965
DBA-ZRR75W			27,672
DBA-ZRR70W			3,266
DBA-ZRR75W			5,321

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-ZRR70G	[NOAH] [VOXY]	2011-2012	59,407
DBA-ZRR70W			78,248
DBA-ZRR75G			10,038
DBA-ZRR75W			16,816
DBA-ANH20W	[ALPHARD] [VELLFIRE]	2010	54,470
DBA-ANH25W			10,819
DBA-GGH20W			6,772
DBA-GGH25W			4,884
DBA-ANH20W		2011-2012	71,759
DBA-ANH25W			13,911
DAA-ATH20W			23,773
DBA-GGH20W			8,662
DBA-GGH25W			4,350
DBE-NCP50V	[PROBOX]	2012	9,240
CFE-NCP52V QFE-NCP52V			40
DBE-NCP51V	[PROBOX] [SUCCEED]	2012	19,724
DBE-NCP55V			8,970
DBA-NCP58G			3,543

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-NCP59G	[PROBOX] [SUCCEED]	2012	1,321
DBA-AZE154H	[BLADE]	2010	224
DBA-AZE156H			1,003
DBA-GRE156H			76
DBA-AZE154H			178
DBA-AZE156H			624
DBA-GRE156H			51
DBA-AZE154H		2011-2012	355
DBA-AZE156H			994
DBA-GRE156H			107
DBA-KSP92	[BELTA]	2012	76
CBA-NCP96			906
DBA-SCP92			432
			168
			1,729
	TOTAL		725,999