

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2478	Date	May 24, 2017
MANUFACTURER	Volkswagen (Japanese Importer: Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	On vehicles of a certain production period, the mixture ratio of the igniting material for airbags and seat belts with belt tensioner has some deviation. As a result, the airbag or the belt tensioner might not operate properly in the event of an accident.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-3CCHH	VW Passat Sedan 2.0/162kW	MY2017	4
	VW Passat Variant 2.0/162kW	MY2017	6
ABA-5NCZE	VW Tiguan 1.4/110kW	MY2017	6
ABA-AUCHH	VW Golf GTI /162kW	MY2017	3
ABA-AUCJSF	VW Golf Alltrack 1.8/132kW	MY2017	4
ABA-AUCJX	VW Golf GTI Clubsport	MY2017	3
ABA-AUCJXF	VW Golf R Variant 2.0/206kW	MY2017	38
DBA-1TCZD	VW Golf Touran 1.4/110kW	MY2017	396
DBA-3CCZE	VW Passat Sedan 1.4/110kW	MY2017	7
	VW Passat Variant 1.4/110kW	MY2017	12

DBA-AUCHP	VW Golf Variant 1.4/103kW	MY2017	16
DBA-AUCJZ	VW Golf 1.2/77kW	MY2017	11
	VW Golf Variant 1.2/77kW	MY2017	3
DBA-AUCPT	VW Golf 1.4/103kW	MY2017	4
DLA-3CCUK	VW Passat Variant GTE	MY2017	18
		Total	531