

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

Campaign No.	Gai-2485	Date	May, 30, 2017
Manufacture	CATERPILLAR JAPAN LLC.		
Description of Deffect	Hydlauric oil leaks on a steering and implement line due to inappropriate assembly procedure modification. Then, it brings hydlauric oil and steering function lost.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDN-FULL	「259D」	2016	6
		TOTAL	6