Vehicle Safety/Pollution Recall Campaign in Japan

Import Vehicles

| Campaign No. Gai- 2516 Date August 3, 2 | 2017 | | | |
|--|-----------------|--|--|--|
| Manufacturer Jaguar Land Rover Limited (Japanese Importer : Jaguar Land Rover Japan Limited) | | | | |
| Description of defect From 2016 to 2017 Model Year Range Rover, Range Rover Range Rover Evoque and Discovery fitted in the Passenger A Module by Autoliv manufactured, reported that deviations can in the generant mix ratio in some initiators. There have been no reported accidents, injuries or fires as a of this concern. | Airbag occur | | | |

| Туре | Commercial name | Model year recalled | | Model year recalled Numb | | Number of vehicles |
|------------|---------------------------------|---------------------|-------|--------------------------|--|--------------------|
| ABA-LG3SB | 「Range Rover」 | 2016 | | ver」 2016 | | 1 |
| ABA-LGL5SC | 「Range Rover」 | 2016 | | 1 | | |
| ABA-LW3SA | 「Range Rover Sport」 | 2016 | | 3 | | |
| CBA-LV2A | BA-LV2A Range Rover Evoque 2017 | | | 2 | | |
| LDA-LR3KA | 「Discovery」 | 2017 | | 1 | | |
| ABA-LR3VA | 「Discovery」 | 2017 | | 1 | | |
| | | | Total | 9 | | |