

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	gai-2535	DATE	October 20, 2017
MANUFACTURE	RENAULT SAS (Japanese Importer : Renault Japon Co., Ltd.)		
DESCRIPTION OF DEFECT	On the wiper linkage rod, due to poor durability of joint point on the linkage rod. There are risk of stopping of the front wiper due to disconnection of the wiper linkage rod from the wiper motor.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-RH4B	「LUTECIA」	2014-2015	286
ABA-RH5F		2013-2015	2,714
ABA-RM5M	「LUTECIA R.S.」	2013-2015	1,468
ABA-RM5M1		2015	6
		TOTAL	4,474