

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	Gai-2557	DATE	2017/Oct./31
MANUFACTURE	FCA Italy S.p.A. (Japanese Importer : FCA Japan Ltd. )		
DESCRIPTION OF DEFECT	The driver airbag module must be replaced because of a potential non-conformity of the supplier's manufacturing process related to the deployment of the second stage firing charge.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-940141	Giulietta	2012	2
		TOTAL	2