

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2578	DATE	2017/12/11
MANUFACTURE	Daimler AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	<p>On certain G-Class vehicles (463 platform) with DISTRONIC PLUS the software of the Electronic Stability Program (ESP) may malfunction under certain conditions. Should the communication between DISTRONIC PLUS and ESP be lost while driving with activated DISTRONIC PLUS (e.g. due to a CAN failure), the current engine torque would be maintained for the duration of the communication loss, regardless of vehicle speed, driving situation or driver brake application.</p> <p>The vehicle can be stopped at all times by braking or by shifting the transmission into neutral. However, significantly increased brake force application might be necessary depending on the actual engine torque. Subsequently, the braking and/or stopping distance might increase.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDA-463348	G350d	2016	2,049
		2017	2,147
ABA-463234	G550	2016	285
		2017	182
ABA-463272	Mercedes-AMG G63	2016	469
		2017	410
-463272-	Mercedes-AMG G65	2016	7
		2017	4
		TOTAL	5,553