VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	Gai-2581	DATE	January 18 2018	
MANUEACTURE	FCA US LLC			
MANUFACTURE	(Japanese Importer : Fiat Chrysler Automobiles Japan Ltd.)			
DESCRIPTION OF DEFECT	Low torque on first or second row seat fasteners could result in squeaks, rattles, deflection or unsatisfactory joint integrity. If not addressed, the condition could potentially lead to compromised structural integrity of the seat.			

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF
	NAME	RECALLED	VEHICLE
ABA-KL24	「Cherokee」	2014	1
ABA-KL32	「Cherokee」	2014	2
ABA-KL32L	「Jeep • Cherokee」	2014	2
		TOTAL	5