## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2590	DATE	2018/1/31		
MANUFACTURE	Daimler AG				
	(Japanese Importer : Mercedes-Benz Japan Co,. Ltd. )				
DESCRIPTION OF DEFECT	On certain S-Class (222 platfor control unit may have been rebracket may be impaired as temperature variations during would be impaired.	ations. The durability of the eak due to vibrations and			
	The internal temperature monit impaired cooling of the transis increased temperatures.		· ·		

TYPE	COMMERCIAL	MODEL YEAR	NUMBER OF
	NAME	RECALLED	VEHICLE
DBA-222182	\$550	2015	1
		TOTAL	1