

## Vehicle Safety/Pollution Recall Campaign in Japan

Import Vehicles

Campaign No.	Gai- 2620	Date	March, 14, 2018
Manufacturer	Jaguar Land Rover Limited ( Japanese Importer : Jaguar Land Rover Japan Limited )		
Description of defect	<p>On certain Right Hand Drive 2016 and 2017 Model Year Range Rover Sport vehicles the Emergency Locking Retractor in the front passenger safety belt assembly may not function correctly.</p> <p>The Emergency Locking Retractors are equipped with a vehicle-sensitive locking mechanism and a webbing-sensitive locking mechanism. Due to a supplier manufacturing issue, the vehicle-sensitive locking mechanism may not lock as designed. In the event of a pre-crash brake event prior to a crash where the passenger airbag deploys, front passenger seat forward facing child seat occupants may sustain more severe injuries.</p>		

Type	Commercial name	Model year recalled	Number of vehicles
ABA-LW3SA	「Range Rover Sport」	2016-2017	68
ABA-LW5SA	「Range Rover Sport」	2016-2017	30
Total			98