

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4211	DATE	March 15,2018
MANUFACTURER	Mazda E&T Co.,Ltd.		
DESCRIPTION OF DEFECT	The designs for the slope hinge and the vehicle body mounting bracket are improper for the vehicle with boarding slope device for wheelchairs. Therefore, the hinge may crack by the repeated opening and closing slope and the loading and unloading wheelchairs. The hinge may break and the slope lean to one side with continued use. In the worst case, the wheelchair users and/or caretakers may fall down.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-MK32S (revision)	Suzuki Spacia	2013 – 2017	3,402
DAA-MK42S (revision)		2015 – 2017	1,427
DBA-MM32S(revision)	Mazda Flair Wagon	2013 – 2017	864
		TOTAL	5,693