

Vehicle Safety/Pollution Recall Campaign in Japan

Import Vehicles

Campaign No.	Gai -2646	Date	April. 17, 2018
Manufacturer	Jaguar Land Rover Limited (Japanese Importer : Jaguar Land Rover Japan Limited)		
Description of defect	<p>2014 and certain 2015 Model Year Range Rover Evoque and certain 2015 Model Year Land Rover Discovery Sport vehicles may have insufficient crimps in a transmission wiring harness which may cause an unexpected shift to neutral resulting in a sudden loss of motive power.</p> <p>The customer may experience a sudden loss of motive power.</p>		

Type	Commercial name	Model year recalled	Number of vehicles
CBA-LV2A	「Range Rover Evoque」	2014 - 2015	1,939
CBA-LC2A	「Discovery Sport」	2015	6
Total			1,945