VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN



CAMPAIGN No.	gai-2643	DATE	Apr. 26, 2018
MANUFACTURER	DUCATI MOTOR HOLDING SpA		
	(Japanese Importer : DUCATI JAPAN Ltd.)		
DESCRIPTION OF DEFECT	In the engine starting system, since the strength of the cage of the starter		
	clutch attached to the flywheel is insufficient, the starter clutch is		
	damaged while repeating starting, and in the worst case the engine can		
	not start.		
	The official Ducati deale	er will replace the st	tarter clutch with a modified
	part. This will be perform	ed free of charge	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBL-GA01	XDiavel XDiavelS	2016-2017	352
		TOTAL	352