

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No	4252	DATE	10th - May -2018
MANUFACTURER	Yano Special Vehicle Co., Ltd. 4-2-1 Kaminofukita Shingu Kasuya-Gun, Fukuoka 811-0123 Japan		
DESCRIPTION OF DEFECT	In a refrigerated freezer car, there are some cases where adhesion is insufficient because the mounting instructions of the rivet cover on the side of the load box are inappropriate. Therefore, when the load box deforms due to temperature change, the rivet cover may be lifted from the load box, and in the worst case, the rivet cover may fall off and interfere with other traffic.		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
BDG-FS1EWYG	PROFIA	2017	1
QPG-FS1EWEJ		2017	3
QKG-FR1EXEG		2017	2
QPG-FR1EXEG		2016~2017	73
QPG-FR1EXEJ		2015~2017	38
QPG-FR1EZEG		2016~2017	21
QPG-FR1EZEJ		2016~2017	12
QPG-FQ1EWEG		2017	1
QPG-FQ1EWEJ		2016	4
QPG-FW1EXEG		2016~2017	29
QPG-FW1EXEJ		2015~2017	12
QPG-FW1EYEG		2016	1
QPG-FW1EYEJ		2017	3
QPG-FW1EZEG		2016~2017	4
LKG-FTR90T2		FORWARD	2017
QPG-CXY77BJ	GIGA	2017	1
QKG-CYJ77B		2016~2017	5
QPG-CYJ77B		2016~2017	12
QKG-CYJ77BA		2016	2
QPG-CYJ77BA		2016~2017	5
QKG-CYL77B		2016~2017	25
QPG-CYL77B		2016~2017	49
QKG-CYL77BA		2016~2017	10
QPG-CYL77BA		2016~2017	21
QKG-CYY77BJ		2017	1
QKG-CYY77BY		2016	1
QPG-CYY77BY		2016	3

TYPE	COMMERCIAL NAME	MODEL TEAR RECALLED	NUMBER OF VEHICLE
QPG-FS64VZ	SUPER GREAT	2015~2017	21
QPG-FU64VY		2017	2
QPG-FU64VZ		2015~2017	57
QPG-FY64VY		2016	1
QPG-FS65VZ		2016~2017	10
QPG-FU65VZ		2015~2017	22
2PG-FS74GZ		2017	1
2PG-FU74GZ		2017	1
2PG-FU74HZ		2017	2
2PG-FY74GY		2017	1
QKG-CD5ZA		QUON	2017
QPG-CD5ZA	2016~2017		41
QKG-CD5ZE	2016~2017		2
QPG-CD5ZE	2016~2017		11
QKG-CG5ZA	2017		1
QPG-CG5ZA	2016~2017		2
QPG-CG5ZE	2015~2017		3
LDG-H3RTF1	VOLVO	2017	5
QDG-LB6X2MLB	SCANIA	2015~2017	1
			TOTAL 525