

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4277	DATE	May. 31. 2018
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	<p>On certain side hanging type spare tire carrier of middle-duty trucks,</p> <p>① due to the improper shape of the hanger, if the spare tire with an aluminum wheel is hung on the carrier, the tire may revolve by the vibration while driving. Therefore, the chain of the carrier may be twisted off, resulting the spare tire to drop.</p> <p>② due to the improper welding of the rolling up equipment, the weld quality may be uneven, causing the safety ratio of the weld strength to be insufficient. Therefore, when the spare tire is hung, if it is tightened with overtorque, not according to the proper tightening method, the welding part may break, resulting the spare tire to drop.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SKG-FC7JHAG TKG-FC7JHAG TPG-FC7JHAG	[HINO Ranger]	2011~2017	55
SKG-FC7JJAG TKG-FC7JJAG TPG-FC7JJAG		2011~2017	312
SKG-FC7JKAG TKG-FC7JKAG TPG-FC7JKAG		2011~2017	767
SKG-FC7JLAG TKG-FC7JLAG TPG-FC7JLAG		2011~2017	102
SKG-FC7JNAG TKG-FC7JNAG TPG-FC7JNAG		2011~2017	30
SKG-FC9JGAG TKG-FC9JGAG		2011~2017	73
SKG-FC9JHAG TKG-FC9JHAG		2011~2017	74
SKG-FC9JJAA SKG-FC9JJAG TKG-FC9JJAA TKG-FC9JJAG		2011~2017	1, 112
SKG-FC9JKAG TKG-FC9JCAA TKG-FC9JKAG		2011~2017	2, 083

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SKG-FC9JLAG TKG-FC9JLAG	[HINO Ranger]	2011~2017	147
SKG-FC9JNAG TKG-FC9JNAG		2011~2017	59
SKG-FC9JSAG TKG-FC9JSAG		2011~2016	47
SKG-FD7JGAG TKG-FD7JGAG TPG-FD7JGAG		2011~2017	28
SKG-FD7JJAG SKG-FD7JJAJ TKG-FD7JJAG TKG-FD7JJAJ TPG-FD7JJAG TPG-FD7JJAJ		2011~2017	182
SKG-FD7JKAG SKG-FD7JKAJ TKG-FD7JKAG TKG-FD7JKAJ TPG-FD7JKAG		2011~2017	731
SKG-FD7JLAA SKG-FD7JLAG SKG-FD7JLAJ TKG-FD7JLAA TKG-FD7JLAG TKG-FD7JLAJ TPG-FD7JLAA TPG-FD7JLAG TPG-FD7JLAJ		2011~2017	9,653
SKG-FD7JMAG SKG-FD7JMAJ TKG-FD7JMAG TKG-FD7JMAJ TPG-FD7JMAG		2011~2017	727
SKG-FD7JPAG TKG-FD7JPAG TKG-FD7JPAJ TPG-FD7JPAG TPG-FD7JPAJ		2011~2017	1,144

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
SKG-FD7JUAG TKG-FD7JUAG TPG-FD7JUAG	[HINO Ranger]	2011~2017	639
TKG-FD7JWAA		2012~2017	16
SKG-FD9JJAG TKG-FD9JJAG		2011~2017	43
SKG-FD9JKAG TKG-FD9JKAG		2011~2017	98
SKG-FD9JLAG TKG-FD9JLAA TKG-FD9JLAG		2011~2017	3,260
SKG-FD9JMAG TKG-FD9JMAG		2011~2017	160
TKG-FD9JPAA		2013~2017	24
SKG-GC7JKAG TKG-GC7JKAG		2011~2017	68
TKG-GC7JLAA		2016	2
SKG-GC9JJAG TKG-GC9JJAG		2011~2017	17
SKG-GC9JAAA SKG-GC9JKAG TKG-GC9JKAG		2011~2017	20
SKG-GC9JLAG TKG-GC9JLAG		2011~2017	59
SKG-GC9JNAA TKG-GC9JNAA		2011~2017	10
SKG-GD7JJAG TKG-GD7JJAG		2011~2017	59
SKG-GD7JKAG TKG-GD7JKAG		2011~2017	51
SKG-GD7JLAG TKG-GD7JLAG		2011~2017	375
SKG-GD7JMAG TKG-GD7JMAG		2011~2017	178
SKG-GD7JPAG TKG-GD7JPAG		2011~2017	257
TKG-GD7JUAA		2012~2017	27
2KG-FC2ABA 2KG-FC2ABG 2PG-FC2ABG		2017~2018	1,055

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2KG-FD2ABA 2KG-FD2ABG 2KG-FD2ABJ 2PG-FD2ABA 2PG-FD2ABG 2PG-FD2ABJ	[HINO Ranger]	2017~2018	3,224
2KG-GC2ABA 2PG-GC2ABA 2DG-GC2ABG 2KG-GC2ABG 2PG-GC2ABG		2017~2018	20
2KG-GD2ABA 2KG-GD2ABG 2PG-GD2ABG		2018	15
		TOTAL	27,003