

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	Gai-2698	DATE	July 20 2018
MANUFACTURE	FCA US LLC (Japanese Importer : Fiat Chrysler Automobiles Japan Ltd.)		
DESCRIPTION OF DEFECT	The brake booster water shield on vehicles may have been incorrectly installed during completion of Safety Recall P14 (NHTSA 14V-154). An incorrectly installed brake booster water shield may be less effective in diverting water away from the brake booster, creating the possibility for corrosion and subsequent water intrusion of the brake booster. Water intrusion of the brake booster in a cold climate may lead to freezing and limit the braking ability of a vehicle. Limited braking ability can cause a vehicle crash without prior warning.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-WK36	「Jeep・Grand Cherokee」	2011-2012	1756
ABA-WK36A	「Jeep・Grand Cherokee」	2011-2012	1145
ABA-WK36T	「Jeep・Grand Cherokee」	2014	115
ABA-WK36TA	「Jeep・Grand Cherokee」	2014	106
ABA-WK57A	「Jeep・Grand Cherokee」	2012-2013	140
-WK57A-	「Jeep・Grand Cherokee」	2013-2014	183
		TOTAL	3445