

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2674	DATE	July 26th, 2018
MANUFACTURE	MV AGUSTA (Japanese importer: MV AGUSTA JAPAN CO., LTD.)		
DESCRIPTION OF DEFECT	Due to an inappropriate material of the piston in the front brake master cylinder, it might be lesser strength. Cracks might be generated on the part by the brake fluid pressure when braking operation, if it is kept using with this condition, cracks grow and make the liquid pressure down. In the worst case, front brake might not work.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZCGF620	F4 RR	2015-2017	17
ZCGF620	F4 RC	2015-2017	43
		TOTAL	60