

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2717	DATE	2018/9/13
MANUFACTURE	Daimler AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	On certain GL/GLE and GLE Coupé vehicles (166, 292 platform) vehicles with Active Curve System the oil in the system's oil reservoir could start foaming under dynamic driving situations in combination with an oil level below minimum. The oil foam might leak out of the oil reservoir through the vent holes of the sealing cap. Depending on the orientation of the vent holes in the sealing cap, leaking oil might spray onto hot components of the exhaust system. In this case the risk of a fire cannot be excluded.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
CBA-166874	GL63 4MATIC	2013	48
		2014	140
		2015	79
		2016	70
		2017	2
CBA-166064	Mercedes AMG GLE43 4MATIC Coupe	2016	53
		2017	3
CBA-166074	Mercedes AMG GLE63S 4MATIC	2012	3
		2013	189
		2014	58
		2015	22
		2016	116
		2017	2
	Mercedes AMG GLE63S 4MATIC Coupe	2016	46
		2017	2
		TOTAL	833