

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4352	DATE	Oct. 11, 2018
MANUFACTURER	SUBARU CORPORATION		
DESCRIPTION OF DEFECT	During the final vehicle inspection in the vehicle assembly plants, there is a possibility that uncertain acceptance/rejection judgment was being performed in the final inspection process. Therefore, the inspection related to the Japanese Safety Regulation under the Japan's Road Transport Vehicle Act was not performed appropriately.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-VM4	「LEVORG」	2017	593
DBA-VMG		2017	199
DBA-VAG	「WRX」	2017	249
CBA-VAB		2017	222
DBA-GK2	「IMPREZA」	2017	52
DBA-GK3		2017	42
DBA-GK6		2017	116
DBA-GK7		2017	173
DBA-GT2		2017	337
DBA-GT3		2017	161
DBA-GT6		2017	360
DBA-GT7		2017	473
DBA-GT3	「XV」	2017	260
DBA-GT7		2017	852
DBA-SJ5	「FORESTER」	2017	709
DBA-SJG		2017	151
DBA-BN9	「LEGACY」	2017	130
DBA-BS9		2017	543
DBA-YAM	「EXIGA」	2017	151
DBA-ZC6	「BRZ」	2017	106
DBA-ZN6	「86」	2017	245
		TOTAL	6,124