

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	Gai-2743	DATE	Nov 02 2018
MANUFACTURE	FCA US LLC (Japanese Importer : Fiat Chrysler Automobiles Japan Ltd. )		
DESCRIPTION OF DEFECT	The rear under body ladder rail may corrode, possibly reducing the strength of the rear floor pan and causing the left rear seat mount to become loose.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-JK36L	「Wrangler Unlimited」	2018	18
		TOTAL	18