## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

**Domestic Vehicles** 

CAMPAIGN No.	4369	DATE	Nov. 8, 2018
MANUFACTURER	SUBARU CORPORATION		
DESCRIPTION OF DEFECT	During the final vehicle inspection in the vehicle assembly plants, there is a possibility that uncertain acceptance/rejection judgment was being performed in the final inspection process. Therefore, the inspection related to the Japanese Safety Regulation under the Japan's Road Transport Vehicle Act was not performed appropriately.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-VM4	「LEVORG」	2018	11,110
DBA-VMG		2018	2,846
DBA-VAG	「WRX」	2018	3,131
CBA-VAB		2018	2,813
DBA-GK2		2018	940
DBA-GK3		2018	757
DBA-GK6		2018	1,099
DBA-GK7		2018	1,754
DBA-GT2	「IMPREZA」 -	2018	5,508
DBA-GT3		2018	3,791
DBA-GT6		2018	3,224
DBA-GT7		2018	4,886
DBA-GT3		2018	7,089
DBA-GT7	ΓXV」	2018	14,278
5AA-GTE		2018	983
DBA-SJ5		2018	6,496
DBA-SJG	[FORESTER.	2018	1,609
5BA-SK9	「FORESTER」 - -	2018	10,511
5AA-SKE		2018	5,476
DBA-BN9	[LECACY)	2018	1,514
DBA-BS9	「LEGACY」	2018	4,901
DBA-YAM	「EXIGA」	2018	988
DBA-ZC6	「BRZ」	2018	1,297
DBA-ZN6	۲86J	2018	3,763
		TOTAL	100,764