

**VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN**

Domestic Vehicles

<b>CAMPAIGN No.</b>	<b>4389</b>	<b>DATE</b>	<b>December 13, 2018</b>
<b>MANUFACTURER</b>	<b>SUZUKI MOTOR CORPORATION</b>		
<b>DESCRIPTION OF DEFECT</b>	At the final inspection for Japanese type approved motorcycle, the result of the brake system inspection and the speedometer accuracy inspection were uncertain, and the confirmation process of the conformity with the safety standards of the Japanese road transport vehicle might not be carried out appropriately.		

<b>TYPE</b>	<b>COMMERCIAL NAME</b>	<b>MODEL YEAR RECALLED</b>	<b>NUMBER OF VEHICLE</b>
2BJ-DL33B	GSX-R125	2018	40
2BJ-DL32B	GSX-S125	2018	7
2BJ-DV12B	SWISH	2018	7
2BJ-DT11A	ADDRESS	2018	2
2BJ-CE47A	ADDRESS 110	2018	1
2BK-DS11A	V STROM	2018	5
2BK-CH41A	BURGMAN	2018	1
2BH-CA4AA	LET'S	2018	1
2BH-CA4BA	ADDRESS V50	2018	1
<b>TOTAL</b>			<b>65</b>