

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4406	DATE	December.18, 2018
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	Fuel cell electronic control unit (FC – ECU) may, due to faults in the fuel cell stack failure detection program, falsely detect the fuel cell stack’s cell voltage drop while the high-voltage battery is fully charged as the fuel cell stack deterioration. Should this happen, the warning light and warning indicator would come on, the fuel cell system would go off, and the vehicle could be disabled in the very worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZBA-ZC4	「CLARITY」	2015~2018	218
		TOTAL	218