

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2790	Date	February 28, 2019
MANUFACTURER	Volkswagen (Japanese Importer: Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	In the interior lighting of the panorama sliding roof, because the design of the electric circuit of fuse is improper, when water accumulates due to drain failure of the sliding roof, water enters the circuit. As the result, due to the effect of the staying water, there is a possibility that the short-circuited in the circuit, and in the worst case, conditions a vehicle fire can occur.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-1TCZD	Golf Touran 1.4L	MY2016-2018	491
LDA-1TDFG	Golf Touran TDI	MY2018	6
ABA-5NCZE	Tiguan 1.4L	MY2017-2018	369
LDA-5NDFGF	Tiguan TDI	MY2018	8
		Total	874