

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2795	DATE	8th.March. 2019
MANUFACTURER	Ferrari SpA (Japanese Importer: Ferrari Japan K.K.)		
DESCRIPTION OF DEFECT	Due to the improper production process, the fuel vapor leaks from the joint of the fuel vapor separator. Consequently there is a risk of fire in worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-F142B	「488GTB」 「488Spider」 「J50」	2017-2018	355
ABA-F151BME	「GTC4 Lusso」	2017-2018	57
ABA-F151CME	「GTC4 Lusso T」	2017-2018	48
ABA-F142BL	「488Pista」	2018	19
ABA-F152BCE	「812 Superfast」	2017-2018	109
AAA-F150ADE	「La Ferrari Aperta」	2018	1
		TOTAL	589