

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2796	DATE	8 <sup>th</sup> .March.2019
MANUFACTURER	Ferrari SpA (Japanese Importer: Ferrari Japan K.K.)		
DESCRIPTION OF DEFECT	The current layout of the Bowden cable creates tension on the door lock mechanism which may cause the cable retaining slot to break and prevent the door from being opened when using the external handle.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-F151BME	GTC4 Lusso	2016-2018	129
ABA-F151CME	GTC4 Lusso T	2017-2018	83
		TOTAL	212