

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIN No.	Gai – 2802	DATE	22 March, 2019
MANUFACTURER	Dr. Ing. h.c. F. Porsche AG (Japanese Importer: Porsche Japan KK)		
DESCRIPTION OF DEFECT	Due to an inadequate connection between the lower longitudinal member and cross member, legal requirements relating to the integrity of the fuel system will not be met in the event of a head-on collision.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-982H1	718 Boxster	2017	561
	718 Cayman		336
ABA-982H2	718 Boxster S		178
	718 Cayman S		143
ABA-982J1	718 Boxster	2018	203
		2019	143
	718 Cayman	2018	1117
		2019	66
ABA-982J2	718 Boxster S	2018	49
		2019	28
	718 Boxster GTS	2018	93
		2019	42
	718 Cayman S	2018	284
		2019	8
	718 Cayman GTS	2018	76
		2019	97
		Total	3424