

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2810	DATE	2019/3/27
MANUFACTURE	Daimler AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	<p>On certain C-Class Coupe/Cabriolet (C/A 205 platform), E-Class Coupe/Cabriolet (C/A 238 platform) and S-Class vehicles (222 platform), the switches in certain seat belt buckles might not have been manufactured according to specifications. A correctly fastened seat belt could be erroneously detected as not fastened.</p> <p>In this case neither the electric (PRE-SAFE®-function) nor the pyrotechnic tensioning would be activated in the event of a crash.</p> <p>Thus, the full effect of the restraint system could be impaired. As a consequence, the risk of injury for occupants would be increased.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-205340	C180 Coupe	2019	124
DBA-205340C			14
DBA-205440	C180 Cabriolet		104
DBA-205440C			4
CBA-205364	Mercedes AMG C43 4MATIC Coupe		12
CBA-205464	Mercedes AMG C43 4MATIC Cabriolet		9
RBA-238342C	E200 Coupe		86
RBA-238442C	E200 Cabriolet		93
DBA-238348C	E300 Coupe		31
DBA-238368	E450 4MATIC Coupe		28

DBA-238468	E450 4MATIC Cabriolet	2019	19
CAA-238361	Mercedes AMG E53 4MATIC+ Coupe		18
CAA-238461	Mercedes AMG E53 4MATIC+ Cabriolet		15
DAA-222158	S450		1
		TOTAL	558