

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2821	Date	April 17, 2019
MANUFACTURER	Volkswagen (Japanese Importer: Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	In a fuel pump with a fuel gauge fitted to a fuel tank, due to the examination of the use environment is insufficient, the pump may be inclined when the fuel tank is expanded due to the influence of the outside temperature. As a result, the remaining amount of fuel can not be detected correctly, or fuel can not be supplied, and in the worst case, there is a risk of engine stalling during vehicle is running.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-3CCZE	Passat Sedan 1.4/110kW	MY2015-2018	3,967
	Passat Variant 1.4/110kW	MY2015-2019	8,595
ABA-3CCHH	Passat Sedan 2.0/162kW	MY2017-2018	369
	Passat Variant 2.0/162kW	MY2017-2019	698
		Total	13,629