

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2844	DATE	May 21 <sup>th</sup> , 2019
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	In the braking systems the rear axle brake caliper components may inadequate coated due to insufficient control during manufacture. The inadequate coating may generates air bubbles in the brake system, and extend the pedal travel while braking. In the worst case the brake performance will be impaired.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-TR20	BMW X3 xDrive 20i	2018	1
LDA-TX20	BMW X3 xDrive 20d	2018	42
TOTAL			15,124