VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

CAMPAIGN No. Gai-2853 DATE May. 28. 2019

MANUFACTURE

BMW
(Japanese Importer: BMW Group Japan Corp.)

DESCRIPTION OF DEFECT

BMW Motorrad has determined that the front brake hose may be damaged over time. This may result in leakages on the brake hose.

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
C600S	「BMW C600 S」	2012-2015	538
C650GT	「BMW C650 GT」	2012-2015	709
EBL-C65AA	「BMW C650 Sport」	2016 -2018	304
EBL-C65AA	「BMW C650 GT」	2016 -2018	393
2BL-C65AA	「BMW C650 Sport」	2018	247
2BL-C65AA	「BMW C650 GT」	2018	291
		TOTAL	2,482

[Ref.] This can also apply to vehicles in which the front brake hose was already replaced as part of Recall GAI-2311.