

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2825	DATE	Jun. 25, 2019
MANUFACTURE	Harley-Davidson Motor Company (Japanese Importer : Harley-Davidson Japan K.K. )		
DESCRIPTION OF DEFECT	Brake calipers (P/Ns 41300158, 41300159 & 41300190) on certain motorcycles may experience corrosion in the caliper bore area if subjected to a corrosive external environment over time, especially in coastal environments or coastal environments where road salt is used. This corrosion could result in the pistons dragging in the caliper bore. If this condition remains undetected it could lead to increased brake drag, possibly resulting in a crash.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBL-XGB	STREET 750	2017	842
2BL-XGB	STREET 750	2017	87
EBL-XGG	STREET ROD	2017	120
2BL-XGG	STREET ROD	2017	441
		TOTAL	1490