## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN



CAMPAIGN No.	4513	DATE	June 27 ,2019	
MANUFACTURER	NIPPON TREX CO., LTD.			
DESCRIPTION OF DEFECT	Regarding the wheel for single tire for semi-trailer, scratches occurs on some of the wheels due to inadequate manufacturing process management. Therefore, cracks will be occurred because of the scratches as a starting point, and air leakage occurs, and in the worst case, there are possibility that the vehicle not be able to continue to run.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
СТВЗ20ЕН	_	2010	1
CTB34003	_	2014	1
PFB34113	_	2011	1
TNF32511	_	2015	2
		TOTAL	5