

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4556	DATE	Aug.28.2019
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In the front passenger airbag inflator of the subject vehicles, due to insufficient protection against moisture absorption into the propellant, there is a possibility that the propellant could degrade after several years of exposure to temperature and moisture fluctuations. In this condition, the inflator may rupture in the event the airbag is activated.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KE-CE121	[COROLLA]	2003-2003	73
UA-NZE120			562
UA-NZE121	[COROLLA] [COROLLA RUNX]		17,169
UA-NZE124	[ALEX]		2,602
UA-ZZE122			1,647
UA-ZZE124			312
TA-ZZE123	[COROLLA RUNX] [ALEX]		284
KE-CE121G	[COROLLA FIELDER]		37
UA-NZE121G			9,207
UA-NZE124G			1,618
TA-ZZE122G UA-ZZE122G			2,173

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TA-ZZE123G	[COROLLA FIELDER]	2003-2003	241
UA-ZZE124G			572
TA-AZR60G	[NOAH] [VOXY]		40,600
TA-AZR65G			11,744
UA-ANH10W	[ALPHARD G] [ALPHARD V]		16,303
UA-ANH15W			5,201
TA-MNH10W			9,022
TA-MNH15W			6,116
ZA-ATH10W	[ALPHARD HYBRID]		1,846
TA-GX110	[MARK II] [VEROSSA]		7,026
TA-GX115			1,121
GH-JZX110 TA-JZX110			2,895
TA-JZX115	[MARK II]		187
TA-GX110W	[MARK II BLIT]		1,130
TA-GX115W			250
GH-JZX110W TA-JZX110W			714
TA-JZX115W			168
UB-NCP50V	[PROBOX]		1,548

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
UP-NCP52V	[PROBOX]	2003-2003	4
UB-NCP51V	[PROBOX] [SUCCEED]		4,220
UB-NCP55V			1,482
UA-NCP58G			3,079
UA-NCP59G			1,072
KP-NLP51V			399
TA-ACM21W UA-ACM21W	[IPSUM]		5,633
TA-ACM26W UA-ACM26W			1,467
UA-NZE127	「WiLL VS」		135
TA-ZZE127			86
TA-ZZE128			65
TA-ZZE129			23
UA-NCP70	[WiLL CYPHA]		3,704
UA-NCP75			529
TA-JCG10	[BREVIS]		1,549
TA-JCG11			402
TA-JCG15		272	
TA-ACM10G	[GAIA]	1,547	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TA-ACM15G	[GAIA]	2003-2003	556
KH-CXM10G			15
TA-ACT10	[OPA]		52
UA-ZCT10 CBA-ZCT10		2003-2004	1,559
UA-ZCT15		2003-2003	227
UA-UZZ40 CBA-UZZ40		[SOARER]	1,143
DBA-UZZ40	「SC430」	2005-2010	3,196
CBA-AZT250	[AVENSIS]	2006-2008	1,980
CBA-AZT251			1,287
CBA-AZT255			494
CBA-AZT250W	[AVENSIS WAGON]		1,175
CBA-AZT251W			1,345
CBA-AZT255W			588
			TOTAL

The affected parts shipped as repair parts, and could not identify the vehicles equipped with them.

PARTS NAME	PARTS NO.	SHIPMENT YEAR	NUMBER OF PARTS	NOTE
Airbag Assembly	73960-12030	2016-2019	5	
	73960-12110		2	

PARTS NAME	PARTS NO.	SHIPMENT YEAR	NUMBER OF PARTS	NOTE
Airbag Assembly	73960-12120	2016-2019	4	
	73960-22010		3	
	73960-22020		1	
	73960-24020		4	
	73960-24040		2	
	73960-28090		26	
	73960-52070		3	
	73960-52100		2	
	73960-52101		4	
	73960-53011		2	
	73960-58010		9	
	73960-58020		25	
	73960-77010		2	
	73970-05090		6	
	73970-12110		5	
	73970-12150		3	
	73970-28080		2	
	73970-44060		2	
		TOTAL	112	