## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	Gai-2911	DATE	September 4, 2019	
MANUFACTURER	Bentley Motors Limited (Japanese Importer : Volkswagen Group Japan KK)			
DESCRIPTION OF DEFECT	On the electric power steering system, its wirings may be trapped between the suspension frame and the under panel due to incorrect route of the wiring harness. Therefore protection tube of the wirings will be rubbed due to vibration whilst driving and warning lamp will be illuminated because the wirings short circuit to the suspension frame. Consequently steering assist function will be lost, in the worst case, it may pose a fire event.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
ABA-BCDDB	Continental GT	2018 - 2019	69