

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	Gai-2921	DATE	Sep 27 2019
MANUFACTURE	FCA US LLC (Japanese Importer : Fiat Chrysler Automobiles Japan Ltd.)		
DESCRIPTION OF DEFECT	A loss of communication between the Occupant Restraint Controller (ORC) and one or more of the acceleration sensors may result in a diminished capability of the air bag system to properly detect certain crash events which may result in degraded inflator outputs, late air bag deployment, or a failure to deploy. If an acceleration sensor loses communication with the ORC, the air bag warning lamp will illuminate in the instrument panel indicating a malfunction in the occupant restraint system. If this warning is not heeded, this condition may increase the risk of injury to vehicle occupants in the event of a crash.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-KL24	「Cherokee」	2019	18
ABA-KL20L	「Cherokee」	2019	113
		TOTAL	131